

Heavy Equipment

Inspection Date Oct 14, 2019 2:52 pm CDT

Job # NA 1814 0184

Ordered Oct 14, 2019 9:45 am CDT

Delivered Oct 15, 2019 11:47 am CDT

Country US



Order Information

Asset ID

not provided

Location

524 Monmouth Road
Millstone, NJ 08510

Equipment Details

VIN (Driver Side Door)

1M1AM07Y1DM013792

Year

2013

Make

Mack

Model

RB

Mileage

592947

Videos

Heavy Equipment

Inspection Date Oct 14, 2019 2:52 pm CDT

Job # NA 1814 0184

Ordered Oct 14, 2019 9:45 am CDT

Delivered Oct 15, 2019 11:47 am CDT

Country US



Engine Running Hood Up (showing timing belts etc)



Truck Moving Forwards and Backwards

Media - Exterior Condition Photos



Front Full View



Driver Side Front Corner Full View



VIN Driver Side Door (if missing take where would appear)

Heavy Equipment

Inspection Date Oct 14, 2019 2:52 pm CDT

Job # NA 1814 0184

Ordered Oct 14, 2019 9:45 am CDT

Delivered Oct 15, 2019 11:47 am CDT

Country US



Driver Side Full View



Rear Full View



Passenger Side Full View



Passenger Side Front Corner Full View

Media - Exterior Damage Photos

Heavy Equipment

Inspection Date Oct 14, 2019 2:52 pm CDT

Job # NA 1814 0184

Ordered Oct 14, 2019 9:45 am CDT

Delivered Oct 15, 2019 11:47 am CDT

Country US



Chip

Media - Interior Condition Photos



Driver Side Interior Full View



Dashboard Full View (key on if available)



Odometer/Hours Reading (key on if required/available)

Heavy Equipment

Inspection Date Oct 14, 2019 2:52 pm CDT

Job # NA 1814 0184

Ordered Oct 14, 2019 9:45 am CDT

Delivered Oct 15, 2019 11:47 am CDT

Country US



Sleeper Cab/Rear Interior 1 (if applicable)



Sleeper Cab/Rear Interior 2 (if applicable)



Passenger Side Interior Full View

Operating Condition

What is the condition of the Interior?

Good

Are there any tears in the upholstery?

No

Are there any strange odors in the vehicle? If so, provide a short description

No

Is there any missing equipment (ie lights etc)? If so, provide details

No
