

Heavy Equipment

Inspection Date Aug 1, 2018 12:10 pm CDT

Job # 0464 8977

Ordered Jul 16, 2018 11:40 am CDT

Delivered Aug 1, 2018 12:22 pm CDT

Country US



Order Information

Asset ID

not provided

Location

1941 Grand Army of the Republic
Highway
Swansea, MA 02777

Equipment Details

VIN (Driver Side Door)

1HSDHSJR7DJ152173

Year

2012

Make

INTERNATIONAL

Model

INTERNATIONAL LF677

Mileage

558938

Videos

Heavy Equipment

Inspection Date Aug 1, 2018 12:10 pm CDT

Job # 0464 8977

Ordered Jul 16, 2018 11:40 am CDT

Delivered Aug 1, 2018 12:22 pm CDT

Country US



Engine Running Hood Up (showing timing belts etc)



Truck Moving Forwards and Backwards


Media - Exterior Condition Photos



Front Full View



Driver Side Front Corner Full View



VIN Driver Side Door (if missing take where would appear)

Heavy Equipment

Inspection Date Aug 1, 2018 12:10 pm CDT

Job # 0464 8977

Ordered Jul 16, 2018 11:40 am CDT

Delivered Aug 1, 2018 12:22 pm CDT

Country US



Driver Side Full View



Rear Full View



Passenger Side Full View



Passenger Side Front Corner Full View

Media - Exterior Damage Photos

Heavy Equipment

Inspection Date Aug 1, 2018 12:10 pm CDT

Job # 0464 8977

Ordered Jul 16, 2018 11:40 am CDT

Delivered Aug 1, 2018 12:22 pm CDT

Country US




Passenger side step



Passenger side damage

Media - Interior Condition Photos



Driver Side Interior Full View



Dashboard Full View (key on if available)



Odometer/Hours Reading (key on if required/available)

Heavy Equipment

Inspection Date Aug 1, 2018 12:10 pm CDT

Job # 0464 8977

Ordered Jul 16, 2018 11:40 am CDT

Delivered Aug 1, 2018 12:22 pm CDT


Country US



Sleeper Cab/Rear Interior 1 (if applicable)



Sleeper Cab/Rear Interior 2 (if applicable)



Passenger Side Interior Full View

Media - Interior Damage Photos



Holder for the visor is broken



Door handle is broken

Operating Condition

What is the condition of the Interior?

Fair

Heavy Equipment

Inspection Date Aug 1, 2018 12:10 pm CDT

Job # 0464 8977

Ordered Jul 16, 2018 11:40 am CDT

Delivered Aug 1, 2018 12:22 pm CDT

Country US



Are there any tears in the upholstery?

No

Are there any strange odors in the vehicle? If so, provide a short description

No

Is there any missing equipment (ie lights etc)? If so, provide details

No
