

# Heavy Equipment

**Inspection Date** Aug 1, 2018 11:37 am CDT

**Job #** 0531 9302

**Ordered** Jul 16, 2018 11:41 am CDT

**Delivered** Aug 1, 2018 11:49 am CDT

**Country** US



## Order Information

Asset ID

not provided

---

## Location

1941 Grand Army of the Republic  
Highway  
Swansea, MA 02777

---

## Equipment Details

VIN (Driver Side Door)

1HSDHSJR9DJ147685

---

Year

2012

---

Make

INTERNATIONAL

---

Model

INTERNATIONAL LF677

---

Mileage

488060

---

## Videos

# Heavy Equipment

**Inspection Date** Aug 1, 2018 11:37 am CDT

**Job #** 0531 9302

**Ordered** Jul 16, 2018 11:41 am CDT

**Delivered** Aug 1, 2018 11:49 am CDT

**Country** US



Engine Running Hood Up (showing timing belts etc)



Truck Moving Forwards and Backwards


## Media - Exterior Condition Photos



Front Full View



Driver Side Front Corner Full View



VIN Driver Side Door (if missing take where would appear)

# Heavy Equipment

**Inspection Date** Aug 1, 2018 11:37 am CDT

**Job #** 0531 9302

**Ordered** Jul 16, 2018 11:41 am CDT

**Delivered** Aug 1, 2018 11:49 am CDT

**Country** US



Driver Side Full View



Rear Full View



Passenger Side Full View



Passenger Side Front Corner Full View

## Media - Exterior Damage Photos

# Heavy Equipment

**Inspection Date** Aug 1, 2018 11:37 am CDT

**Job #** 0531 9302

**Ordered** Jul 16, 2018 11:41 am CDT

**Delivered** Aug 1, 2018 11:49 am CDT

**Country** US



Grille




Grille



Driver side lower step

## Media - Interior Condition Photos



Driver Side Interior Full View



Dashboard Full View (key on if available)



Odometer/Hours Reading (key on if required/available)

# Heavy Equipment

**Inspection Date** Aug 1, 2018 11:37 am CDT

**Job #** 0531 9302

**Ordered** Jul 16, 2018 11:41 am CDT

**Delivered** Aug 1, 2018 11:49 am CDT

**Country** US



Sleeper Cab/Rear Interior 1 (if applicable)



Sleeper Cab/Rear Interior 2 (if applicable)



Passenger Side Interior Full View

## Operating Condition

What is the condition of the Interior?

Good

---

Are there any tears in the upholstery?

No

---

Are there any strange odors in the vehicle? If so, provide a short description

No

---

Is there any missing equipment (ie lights etc)? If so, provide details

No

---