

# Heavy Equipment

**Inspection Date** Jul 18, 2019 2:20 pm CDT

**Job #** NA 0344 1889

**Ordered** Jul 10, 2019 2:34 pm CDT

**Delivered** Jul 18, 2019 3:11 pm CDT

**Country** US



## Order Information

Asset ID

not provided

---

### Location

1389 Portsmouth Boulevard  
Suffolk, VA 23434

---

## Equipment Details

VIN (Driver Side Door)

1FVACWDT7CDBL3913

---

Year

2012

---

Make

Freightliner

---

Model

M2 106 Medium Duty

---

Mileage

256743

---

## Videos

# Heavy Equipment

**Inspection Date** Jul 18, 2019 2:20 pm CDT

**Job #** NA 0344 1889

**Ordered** Jul 10, 2019 2:34 pm CDT

**Delivered** Jul 18, 2019 3:11 pm CDT

**Country** US



Engine Running Hood Up (showing timing belts etc)



Truck Moving Forwards and Backwards

## Media - Exterior Condition Photos



Front Full View



Driver Side Front Corner Full View



VIN Driver Side Door (if missing take where would appear)

# Heavy Equipment

**Inspection Date** Jul 18, 2019 2:20 pm CDT

**Job #** NA 0344 1889

**Ordered** Jul 10, 2019 2:34 pm CDT

**Delivered** Jul 18, 2019 3:11 pm CDT

**Country** US



Driver Side Full View



Rear Full View



Passenger Side Full View



Passenger Side Front Corner Full View

## Media - Exterior Damage Photos

# Heavy Equipment

**Inspection Date** Jul 18, 2019 2:20 pm CDT

**Job #** NA 0344 1889

**Ordered** Jul 10, 2019 2:34 pm CDT

**Delivered** Jul 18, 2019 3:11 pm CDT

**Country** US



Front bumper slightly dented in center

## Media - Interior Condition Photos



Driver Side Interior Full View



Dashboard Full View (key on if available)



Odometer/Hours Reading (key on if required/available)

# Heavy Equipment

**Inspection Date** Jul 18, 2019 2:20 pm CDT

**Job #** NA 0344 1889

**Ordered** Jul 10, 2019 2:34 pm CDT

**Delivered** Jul 18, 2019 3:11 pm CDT

**Country** US



Passenger Side Interior Full View


## Media - Interior Damage Photos



None



Normal wear and tear only



Was not able to take video of engine running or truck moving forward/backwards. Video button was inoperable. Took additional video and will send via email.

## Operating Condition

What is the condition of the Interior?

Good

# Heavy Equipment

**Inspection Date** Jul 18, 2019 2:20 pm CDT

**Job #** NA 0344 1889

**Ordered** Jul 10, 2019 2:34 pm CDT

**Delivered** Jul 18, 2019 3:11 pm CDT

**Country** US



Are there any tears in the upholstery?

One or a few small tears

---

Are there any strange odors in the vehicle? If so, provide a short description

Nonexistent

---

Is there any missing equipment (ie lights etc)? If so, provide details

No

---