

Heavy Equipment

Inspection Date Jul 31, 2019 9:54 am CDT

Job # NA 8187 1324

Ordered Jul 30, 2019 2:48 pm CDT

Delivered Aug 3, 2019 10:30 am CDT

Country US



Order Information

Asset ID

not provided

Location

Brook Forest Avenue
Shorewood, IL

Equipment Details

VIN (Driver Side Door)

4V4NC9EJ3HN970656

Year

2017

Make

Volvo

Model

VNL

Mileage

484142

Videos

Heavy Equipment

Inspection Date Jul 31, 2019 9:54 am CDT

Job # NA 8187 1324

Ordered Jul 30, 2019 2:48 pm CDT

Delivered Aug 3, 2019 10:30 am CDT

Country US



Engine Running Hood Up (showing timing belts etc)



Truck Moving Forwards and Backwards

Media - Exterior Condition Photos



Front Full View



Driver Side Front Corner Full View



VIN Driver Side Door (if missing take where would appear)

Heavy Equipment

Inspection Date Jul 31, 2019 9:54 am CDT

Job # NA 8187 1324

Ordered Jul 30, 2019 2:48 pm CDT

Delivered Aug 3, 2019 10:30 am CDT

Country US



Driver Side Full View



Rear Full View



Passenger Side Full View



Passenger Side Front Corner Full View

Media - Exterior Damage Photos

Heavy Equipment

Inspection Date Jul 31, 2019 9:54 am CDT

Job # NA 8187 1324

Ordered Jul 30, 2019 2:48 pm CDT

Delivered Aug 3, 2019 10:30 am CDT

Country US



Drivers side from headlight and quarter panel scratches



Minor scratches on passenger side door area


Media - Interior Condition Photos



Driver Side Interior Full View



Dashboard Full View (key on if available)



Odometer/Hours Reading (key on if required/available)

Heavy Equipment

Inspection Date Jul 31, 2019 9:54 am CDT

Job # NA 8187 1324

Ordered Jul 30, 2019 2:48 pm CDT

Delivered Aug 3, 2019 10:30 am CDT

Country US



Sleeper Cab/Rear Interior 1 (if applicable)



Sleeper Cab/Rear Interior 2 (if applicable)



Passenger Side Interior Full View

Operating Condition

What is the condition of the Interior?

Good

Are there any tears in the upholstery?

No

Are there any strange odors in the vehicle? If so, provide a short description

The agent did not observe any strange odors in the vehicle.

Is there any missing equipment (ie lights etc)? If so, provide details

The agent did not observe any missing equipment .