

Heavy Equipment

Inspection Date Jun 22, 2020 3:48 pm CDT

Job # NA 8825 8615

Ordered Jun 21, 2020 8:47 am CDT

Delivered Jun 24, 2020 12:20 pm CDT

Country US



Order Information

Asset ID

not provided

Location

312 Reindeer Moss Court
Myrtle Beach, SC 29588

Equipment Details

VIN (Driver Side Door)

40714

Year

not provided

Make

LOAD EAZ

Model

not provided

Mileage

0

Videos

Heavy Equipment

Inspection Date Jun 22, 2020 3:48 pm CDT

Job # NA 8825 8615

Ordered Jun 21, 2020 8:47 am CDT

Delivered Jun 24, 2020 12:20 pm CDT

Country US



Engine Running Hood Up (showing timing belts etc)



Truck Moving Forwards and Backwards


Media - Exterior Condition Photos



Front Full View



Driver Side Front Corner Full View



VIN Driver Side Door (if missing take where would appear)

Heavy Equipment

Inspection Date Jun 22, 2020 3:48 pm CDT

Job # NA 8825 8615

Ordered Jun 21, 2020 8:47 am CDT

Delivered Jun 24, 2020 12:20 pm CDT

Country US



Driver Side Full View



Rear Full View



Passenger Side Full View



Passenger Side Front Corner Full View

Media - Interior Condition Photos

Heavy Equipment

Inspection Date Jun 22, 2020 3:48 pm CDT

Job # NA 8825 8615

Ordered Jun 21, 2020 8:47 am CDT

Delivered Jun 24, 2020 12:20 pm CDT

Country US



Driver Side Interior Full View



Dashboard Full View (key on if available)



Odometer/Hours Reading (key on if required/available)



Passenger Side Interior Full View

Operating Condition

What is the condition of the Interior?

Good

Are there any tears in the upholstery?

No

Heavy Equipment

Inspection Date Jun 22, 2020 3:48 pm CDT

Job # NA 8825 8615

Ordered Jun 21, 2020 8:47 am CDT

Delivered Jun 24, 2020 12:20 pm CDT

Country US



Are there any strange odors in the vehicle? If so, provide a short description

None

Is there any missing equipment (ie lights etc)? If so, provide details

None
